

Anthony Field



Town of Fairhaven ADA Transition Plan

November 2024



Institute for Human Centered Design

560 Harrison Ave, Unit 401, Boston, MA 02118
www.IHCDesign.org • info@IHCDesign.org
617-695-1225 voice/ tty

Background

Anthony Field is located at 35 North Street with an approximately 110 foot long stretch of Castle Avenue connecting to a parking lot for the Anthony Haven housing facility which runs along the west side of Anthony Field. Amenities include a softball field and a basketball court.





Exterior locations surveyed included the softball field and the basketball court.

Key Accessibility Issues

Exterior Access Route

Key accessibility issues include lack of an accessible route to the boundary of sport activity and to the team seating at the softball field. There is also lack of an accessible route to the boundary of sport activity at the basketball court, and the basketball court is not maintained in operable working condition.

***Note:** IHCD is not providing costs for exterior issues such as estimating the cost to provide walkways.

ID	Location	Floor	Room	Element	Type	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
Approach and Entrance												
Exterior Access Route												
1	Softball Field Entrance on Castle Avenue	Ext.		Exterior Access Route	Walkway		Not provided from all site arrival points	-	Ensure a stable, firm and slip resistant accessible route is provided from the site arrival point to the boundary of sport activity at the softball field.	1	-	-
Play and Sport Areas												
Field												
2	Softball Field First and Third Base Team Seating	Ext.		Field	Softball		Accessible spaces not provided at team seating No accessible route to all areas of sport activity	- -	Provide a 36" x 48" stable, firm and slip resistant clear ground space at team seating. Install an accessible route to the team seating and between all areas of sport activity.	2	-	-
Court												
3	Field/Route To Basketball Court	Ext.		Court	Basketball		Court is not connected to an accessible route		Provide a stable, firm and slip resistant accessible route to the boundary of sport activity at the basketball court starting from the site arrival point.	1	-	-
4	Basketball Court	Ext.		Court	Basketball		Court not maintained in operable working condition	-	Ensure that the court is maintained in operable working condition.	1	-	-